

Ben Hughes Communication Products Company
P.O. Box 373, 207 Middlesex Avenue
Chester, CT 06412-0373 USA
800-394-4046/860-526-4337/Fax 860-526-2291
WEBSITE: www.cableprep.com EMAIL: toolmaker@cableprep.com

Mid Span Stripper P/N 500-MSS

Preparation Instructions

1. Open tool by releasing lever.
2. Place over cable and snap closed
3. Rotate the tool by pushing the snap lever with thumb. (See Fig. A.) For Optimal Results: Ensure rotation of tool follows the feed direction as noted in Fig. B.
4. When desired amount of jacket has been removed, stop directional pressure and spin the tool freely to cut off excess jacket.
5. Pull back snap lever and remove tool from cable.

← Rotate




Fig. A

← Feed




Fig. B

NOTE: In cases where cable variations cause strip blade to come in contact with the aluminum sheath, the spring washer stored under the screw head may be installed under the jacket strip blade. (Hex key is enclosed with tool.)